فرخور ا	JSE CARNIGES		. ;	470 PM	
.3	Ecitions	CLASSIFIED MESSAGE	<i>*</i>	rosa – ar jerosemania je sasaljevome Liguesiniam ROLTING	
			1	9	
ATE	0123Z 17 QEC 64	SECRET	2	10	
	· ·		[3 4	11 12	
25X1	Α		5	13	
		ROUTING INT	6	14	
3 :	DIRECTOR		7	15	
ROM			8	16	
CTION:			PRIORITY		
FO :		6			
		8	Sal	:	
	TOR: 0206Z 17 DEC 64	9	BIN	IN 63097	
	•	10	SA 1-15		
25X1/	4		dr 1-10		
1	PRIORITY INFO		CITE		
3 25X1/	A LANGE TO SERVE TO S		Ç		
	OXCART FLTEST OPS		<u></u>	$m \cdot \rho$	
25X1	Δ		-ca-cre on (•	
20/(1/	N ARTICLE 127 MADE	FLIGHT 95 SORTIE 1-T	-04-00 B OM	O DEC 04.	
i	TAKEOFF AT 1000 HOURS, LANDING AT 1250 HOURS				
	OR 2:56. MISSION UNSUCCESSFUL. GROSS WEIGHT 117,000 LBS, C.G.				
20.3 PERCENT, TAKEOFF DISTANCE 7500 FT, TAKEOFF SPEED 220 KN				NOTS.	
	·	PARTY INNEOFF DISTRICE FOREST STATES OF ELD AND TO			
PRESSURE ALT 4450 FT, TEMP 27 DEGREES, WIND CALM. MAX SPEED MACH, MAX ALTITUDE 77,000 FT, TIME OVER 2.0 MACH 1:50, TIME O				EED 2.8	
				ME UNE	
	MACH, MAX ALITIUDE //pt	W WEITINGS LIBERS LIB LIKE CARL SOR LIBOU ISAND LINE CARL			
	2.6 MACH 1:30, TIME OVE	230, TIME OVER 2.8 MACH N/A, TOTAL AIRCRAFT TIME 135:57.			
25X1	Α			•	
	PURPOSE: CONFIGURATION 2.8 MACH.				
Q BAY AND SPECIAL EQUIPMENT: TYPE I PACKAGE. 2. SUMMARY: NORMAL TAKEOFF AND CLIMB. ON BOTH CLIMBOUTS					
				BOUTS	
	MODERATE TO SEVERE TURBULENCE WAS ENCOUNTERED BETWEEN 49,000 AND 50,000 FT. INS AUTONAV-AUTO DESTINATION USED AND APPEARED GOOD. AN ACTUAL ARC-50 RENDEZVOUS WAS ACCOMPLISHED IN EXTERNAL MODE. CONINUOUS DIE FROM 450NM TO 1NM, AT THIS TIME VOICE CONTACT WAS				
- Note to the Control of the Contr					
	MADE AND AIR REFUELING WAS ACCOMPLISHED IN EXTERNAL MODE. GOOD				

USAF review(s) completed.

Approved For Release 2004/05/15; CIA-RDP 9B00986R000380060043-9

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

ADF FROM 150NM TILL CONTACT.

AIR REFUELING ACCOMPLISHED IN A

25X1A

DESCENT FROM 30,000 TO 24,000 FT WITH AN ONLOAD OF 60,000 LBS.

ON SECOND CLIMBOUT FAILURE OF B HYDRAULIC SYSTEM OCCURED AND MISSION WAS ABORTED. SSB CONTACTS WERE GOOD. ON LANDING, CHUTE DEPLOY/
JETTISON NORMAL. LIFE SUPPORT EQUIPMENT WAS SATISFACTORY.

END OF MESSAGE